

# Boeing 767 shot on approach in Brazil

Declan Selleck  
25 January, 2017

Details still emerging: this page will be updated. Report any information to [report@safairspace.net](mailto:report@safairspace.net).

25 JAN - Information updated.

At **Flight Service Bureau** we rarely report on individual aircraft incidents, because the impact to other operators in International Flight Operations is very minimal. This case is different.

We received an OPSGROUP member report of an incident that occurred around January 15th, to a B767-300 operated by Latam Airlines, on approach.

Our initial report indicated that the 767 was fired upon on approach to Runway 15 at SBGL/GIG – the main Rio de Janeiro airport. A 7.62mm bullet lodged in the No. 3 slat, on the left wing. Pictures are below. Subsequent reports from other sources suggest that it may have occurred in Sao Paolo.

The specific location in Brazil is therefore uncertain, but anecdotal evidence suggests that the aircraft overflew a favela on approach, and that Rio remains the most likely candidate for the location.

Rio Airport has however asked us to publish this statement:

**RIOgaleão**, concessionaire responsible for the operation of Tom Jobim International Airport, in Rio de Janeiro (Brazil), informs that there has not been any record of an aircraft hit by a bullet within the airport site. The airline's press office, in a statement, informed to the Brazilian press that it has activated the national and aviation security agencies. The public agencies investigate the case to identify where the incident occurred.

An entry for Brazil with the full report has been added to SafeAirspace.net, our shared repository on threats to aviation including Conflict Zones, Airspace Security, and Overflight risk.



B767 PT-MSY



Section of wing with lodged bullet



**PROJÉTIL**



**SELO AERODINÂMICO**

**DIMENSÕES DO PROJÉTIL**

Comprimento: 29,00 mm

Diâmetro: 7,62 mm



**Update:**

**19JAN:** Rio Airport has asked us to publish this statement:

*RIOgaleão, concessionaire responsible for the operation of Tom Jobim International Airport, in Rio de Janeiro (Brazil), informs that there has not been any record of an aircraft hit by a bullet within the airport site. The airline's press office, in a statement, informed to the Brazilian press that it has activated the national and aviation security agencies. The public agencies investigate the case to identify where the incident occurred.*

References:

- Full report under Brazil at [safeairspace.net](http://safeairspace.net)

---

## International Bulletin: B767 shot on


# approach to Rio, Updated SafeAirspace Map

Cynthia Claros  
25 January, 2017

**INTERNATIONAL  
BULLETIN**

**ISSUED BY FLIGHT SERVICE BUREAU**

SITA HNLFSXH AKLFSXH AFTN KMCOXAAL  
EMAIL INTL.DESK@FSBUREAU.ORG



## B767 Shot on approach to Rio

18JAN A B767-300 was fired on last night during approach to Runway 15 SBGL/Rio de Janeiro. One 7.62mm bullet lodged in the left wing. Read the article.

## Updated SafeAirspace Risk Map

18JAN We have updated SafeAirspace with information for Aircraft Operators on The Gambia, North Korea, Brazil, Ukraine, and Turkey.

---

**GBZZ/The Gambia** State of emergency declared on 17th January. Foreign citizens being evacuated. Banjul International Airport (GBYD/BJL) and land borders remain open, for now. More at [safeairspace.net/information/the-gambia](http://safeairspace.net/information/the-gambia).

**UKZZ/Ukraine** Flight Service Bureau has issued an updated summary for Ukraine's airspace. **There are two risk issues in Ukraine.** First: arms fire. Including MH17, multiple aircraft (the others all military) have been shot down since the beginning of the Donbass region war in 2014. The 10th ceasefire was declared in December 2016, but not holding. This risk is contained within the Dnipropetrovsk FIR - UKDV. **The second issue** affects the Simferopol FIR which is **Disputed Airspace**. (Ukraine:UKFV, Russia:URFV). In March 2014, Russia annexed Crimea. The ATC Center is in Simferopol, Crimea, and is now run by Krymaeronavigatsiya. Russia claims the airspace. Ukraine refuses to recognise the change, and asks crews to talk to Ukrainian controllers in Dnipro/Odesa ACC instead of Simferopol ACC. Four routes are approved by EASA through the high seas portion of the airspace.

**KIAD/Washington** and area airports - guaranteed busy during the Presidential Inauguration this Friday, Jan 20. Updated restrictions here. Departure slots required for aircraft departing IAD between Friday, Jan. 20 and Sunday, Jan. 22. Departure slots can be obtained through an IAD FBO of choice (Ross Aviation or Signature Flight Support). Slots will be divided equally between the two FBOs at IAD.

**VZZZ/Southeast Asia** Lunar New Year holiday season, which falls on 28th Jan. Travel-related delays and government office and business interruptions will peak 27 Jan to 01 Feb, and could last longer in Taiwan, Vietnam and China, where the holiday will be celebrated through 02FEB.

**BGBW/Narsarsuaq** A seasonal reminder that if you're planning to use Narsarsuaq as a destination, alternate, or enroute alternate outside of the operating hours (MON-SAT 1000-1900z daily until 03APR), you must contact the airport in advance to apply for them to stay open for you: Email: bgbw@mit.gl. Also make sure you file your ATC FPL including the AFTN address: BGBWZTZX.

**EKCH/Copenhagen** A copy of the AOC must accompany fuel release or expect an MOT charge of approximately \$1.70 USD to be charged. Next destination must be shown on the fuel release or expect delays.

**EGPH/Edinburgh, Scotland** Until Apr 1st, you will need PPR to operate to Edinburgh, due to reduced parking capacity.

**RPLB/Subic Bay** will be closed for maintenance bewtween 0100-0800z until January 20th.

**SKZZ/Colombia** New Tower and ACC for Bogota. From 16th Jan - 15th Feb moving of Bogota's ACC will take place. ATS/AIS/COM/MET/ATFM services transition process should not affect operations, however, due to the large change extent foreseen, some failures might occur in the process. AIC 1/17 outlines contingency procedures in place

**SVZZ/Venezuela** has closed its land borders with Colombia and Brazil periodically in the last 12 months. Border closures occur frequently, often with short notice. The Venezuelan government will withdraw the 100 bolivar note (VEF 100) from circulation as of 20 January 2017.

**LYBA/Beograd** If you have any outstanding navigation fees in Serbia, better get them paid, or they'll add a 9.88% interest charge.

**HSSS/South Sudan** Flight Service Bureau has issued an updated summary for South Sudan's airspace: Conflict Zone. South Sudanese Civil War since 2013. The security situation in Juba has been relatively calm since the July 2016 crisis. Daily reports of fighting throughout the rest of the country. The security situation is especially unstable in the Equatoria in the south. MANPADS risk to overflights. In addition, the South Sudanese army has declared intention to shoot down Aircraft without permits. Most Authority guidance recommends min FL260. We think FL300 is a better minimum for overflights.

**ZKKP/North Korea** Flight Service Bureau has issued an updated summary for DPRK North Korea's airspace: The level of tension on the Korean peninsula can change with little notice. Multiple missile launches in 2016, increasingly without prior notice to ICAO. The range of these has increased – previously safe airways B467 and G711 are now at risk. Over 1000 reports of GPS jamming issues reported by operators in the vicinity of the North/South Korean border. SFAR79 prevents US operators from operating west of 132E, other Authorities restrict operationseast of that line.

**ZZZZ/Worldwide** How have you been getting on with the new ICAO SID/STAR phraseolgies? In short, some countries are implementing, and others aren't. What is your country doing? Tell us at bulletin@fsbureau.org.

View the full International Bulletin 18JAN2017