

**A0065/18 (Issued for HLLL)** - UNDER THE AUTHORITY OF THE LIBYAN CIVIL AVIATION AUTHORITY THE FOLLOWING CONTINGENCY PROCEDURES FOR TRANSIT TFC IN THE HLLL FIR ARE APPLICABLE TAKING INTO ACCOUNT LIMITATIONS IN ATM/CNS AND SAFETY OF FLIGHT OPERATIONS.

THE PROCEDURES IN THIS NOTAM ARE MANDATORY AND SHALL BE STRICTLY ADHERED TO. PRIOR PERMISSION TO OPERATE INTO HL INTERNATIONAL AERODROMES AND TO OVERFLY HLLL FIR IS REQUIRED BY ADVANCE NOTIFICATION TO THE LIBYAN CAA ON EMAIL:ATD AT CAA.GOV.LY OR BY FAX +218213618075 OR ON AFTN: HLLTYAYA/HLLTYAYX.

HLLB(BENINA) HLLM (MITIGA),HLLQ (LABRAQ),HLMS (MISURATA),AND HLTQ (TOBRUK)ARE AVAILABLE H24 FOR INTERNATIONAL FLIGHTS AND EN-ROUTE DIVERSIONS.HLZW (ZWARA) IS ONLY AVAILABLE FOR NATIONAL FLIGHTS FROM SR TO SS.

MANDATORY ROUTING SCHEME FOR HLLL FIR OVERFLIGHTS. THE FWG ROUTES IN THE HLLL FIR ARE AVBL 24H FOR INTERNATIONAL TRAFFIC TRANSITING THE HLLL FIR. ALL OTHER ATS ROUTES ARE PROHIBITED FOR INTERNATIONAL TRANSIT TRAFFIC THROUGH THE HLLL FIR UFN. INTERNATIONAL FLIGHTS PLANNING TO OPERATE THROUGH THE HLLL FIR ARE ONLY PERMITTED TO FLIGHT PLAN IN ACCORDANCE WITH THE MANDATORY ROUTING SCHEME SPECIFIED IN THIS NOTAM. DEVIATION FROM THESE ATS ROUTES IS ONLY ACCEPTED ON A TACTICAL BASIS AND WHEN REQUIRED FOR SAFETY AND OPERATIONAL REASONS. ANY INFORMATION ABOUT THE UNAVAILABILITY OF THE ATS ROUTES INDICATED BELOW WILL BE PROMULGATED BY NOTAM.

**SOUTHBOUND /EASTBOUND ROUTES:**

VIA ABRAM UN163 GRT A403 SEB UM214 GARIN  
VIA ABRAM UN163 GRT A403 SEB A403F TUMMO  
VIA ABRAM M727 ZAW UM727 DEKIL  
VIA VARIG T299 ZAW UM600 IMN  
VIA LOTIN UL12 TONBA  
VIA FARES UM731 DEKIL  
RASNO UY751 LOSUL  
TANLI A411 PRAWN V400 LAB W861 NASER A411 LOSUL

**NORTHBOUND/ WESTBOUND ROUTES:**

VIA IMN UM600 ZAW M/UM600 SARKI  
VIA TUMMO A403F SEB M740 SARKI  
VIA GARIN UM214 SEB M740 SARKI  
VIA GARIN UP126 LUMED  
VIA TONBA UM215 LUMED

VIA DEKIL UM731 FARES  
LOSUL UP128 LAB UM979 RAMLI UZ270 OLMAX  
LOSUL UP128 TANLI

OPERATORS ARE REQUIRED TO USE THE IATA IN-FLIGHT BROADCAST PROCEDURE (IFBP) WHILE OPERATING IN THE HLLLFIR. PILOTS UNABLE TO MAINTAIN COMMUNICATION WITH ATC ARE REQUIRED TO ESTABLISH DIRECT PILOT- CONTROLLER COMMUNICATION ON THE DEDICATED TELEPHONE NUMBER +218215632331. WHEN COMMUNICATION ON THIS NUMBER IS NOT POSSIBLE PILOTS SHOULD ATTEMPT TO CONTACT ATC ON THE SECONDARY NUMBERS +218213619614.

12 MAY 09:30 2018 UNTIL 12 AUG 10:00 2018 ESTIMATED. CREATED: 12 MAY 09:35 2018.