

# Mexico ADS-B Mandate Coming Soon

OPSGROUP Team  
22 December, 2021



Mexico's ADS-B mandate, delayed a year, is coming into effect **January 1, 2022.**

## Why was it delayed?

Apparently it came down to supply of ADS-B equipment issues meaning a lot of Mexican registered aircraft were unable to get it installed in time.

## What do you need?

Mexico have mandated the use of **1090-MHz Mode S** squitter transponders and as yet have not agreed to extend the mandate to allow 978 MHz Universal access transceivers, which are allowed in the US. The main difference is 978 MHz transponders are not allowed above 18,000' while 1090MHz ones can be used at any altitude.


**The mandate is for ADS-B Out.** If you're unsure on the difference then the FAA have a handy page on it [here](#), but the simplified difference is *Outtie's* broadcast an aircraft's GPS location, altitude, groundspeed etc to ATC ground stations and other aircraft. *Innie's* provide the aircraft with weather and traffic info delivered directly to the flight deck.

## Where will you need it?

The rules look **similar to those in the US:**

- Class A
- Class B
- Class C
- Class E above 10,000 feet

- Class E over the Gulf of Mexico, above 2,500 feet
- Within 12nm of the Mexican coast, above 3,000 feet
- Within 30nm of MMMX/Mexico City International Airport, above 10,000 feet



Easier in a diagram.

### What if mine breaks?

There is a process for operators to **request permission, in advance**, if their ADS-B is inoperative. You can also request to fly without ADS-B equipment installed if you submit the request at least an hour before departure (probably a good idea to do it a little earlier).

### Where is the official info?

All we have discovered so far is this Advisory which unfortunately is in Spanish. **Watch this space** for info on how to request the no ADS-B permission.

### Where else do I need ADS-B?

We have a whole post on 'ADS-B Mandates Around the World' which you can read here.